



# Typical Hose Failures

Steel Hose Jacket twists and breaks off from rigid connector fitting.

Steel spur then cuts into inner soft hose causing it to leak.



## Existing Hose Systems



## GI Flex Hose System Patent Pending



### The Solution

Get rid of the Steel Hose Jacket that breaks and cuts through the Soft Inner Hose.

Replace both with a Flexible Reinforced Hose.

Replace the Rigid Connectors with Swivels for Unlimited Movement.

Now you have an Engineered Hose System that is 15 Times Stronger with an *Industry Leading Two Year Warranty!*



Canadian Innovation – Invented and Designed - Built with Canadian Pride



GI Flex Hose Systems.  
Alberta 403 475 4810 giflex@shaw.ca  
British Columbia 778 294 2918 giflexbc@telus.net

Rev 1  
2/23/2009